


Alternative to CNC:
Lay out and drill 1/4" holes, then
mill, saw, or turn away excess.



3 ROTOR
mat'l - steel

